SCREENING SITE INSPECTION WORK PLAN
FOR
WEST 78th CIRCLE SITE
BLOOMINGTON, MN
U.S. EPA ID: MND980995872

SS ID: NONE TDD: F05-8706-169 PAN: FMN0172GA



JANUARY 19, 1989

Elements of this Screening Site Inspection Work Plan are considered confidential and pre-decisional in nature. Material and information contained within this report may not be released without the approval of the United States Environmental Protection Agency Region V Pre-Remedial Unit.



ecology and environment, inc.

111 WEST JACKSON BLVD., CHICAGO, ILLINOIS 60604, TEL. 312-663-9415 International Specialists in the Environment

recycled paper



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 5

230 SOUTH DEARBORN ST. CHICAGO, ILLINOIS 60604

REPLY TO THE ATTENTION OF

5HR-11

Mr. Ron Swenson
Site Response Section
Minnesota Pollution Control Agency
520 Lafayette Road
St. Paul, Minnesota 55155

Site Name: WEST 78TH CIRCLE SITE Location: BLOOMINGTON, MN

Identification No. MND 980995872

Date: 1-23-89

Dear Mr. Swenson:

Attached is a copy of the site inspection work plan which has been prepared for the site listed above. This document is considered to be <u>draft</u> and subject to changes and modifications based on actual conditions which may be encountered at the site.

Because this is considered to be a draft document, it should be for official use only and should not be distributed outside of your agency without prior notification and approval of the U.S. Environmental Protection Agency.

The document also contains a preliminary estimate of the Hazard Ranking System (HRS) score for the site and a project score based on specific assumptions as addressed in the work plan. This information is considered predecisional. Therefore, it should not be released. Your field and district staff especially should be made aware of the predecisional nature of this score, the legal implications of releasing it relative to the National Priorities List (NPL) candidacy process, and therefore the need not to release any score. If you have any questions concerning release of this information, please contact Ms. Jeanne Griffin, of my staff, at (312) 886-3007.

If you have any comments on the work plan itself, please contact Mr. Charles Castle, of my staff, at (312) 886-5892, within eight calendar days. If we do not receive any comments written or verbal from you, then we will assume that the work plan is acceptable.

Please note that site inspections are carried out under CERCLA to determine if a site will make the NPL. Thus, extra sampling or other activities that serve only a State purpose should not be requested. We welcome suggestions based on the knowledge of you and your staff that will make for a better site inspection for NPL candidacy purposes.

Please talk with Mr. Castle as early within the eight-day period as possible in order that your suggestions can be evaluated and modifications made.

Sincerely yours,

Thomas F. Geishecker, Chief Program Support Section

Homas F. Herskocker

Enclosure

MPCA Staff Comments On Screening Site Inspection Work Plan Prepared By E & E

Site Name: <u>Y</u>	West 78th Circle Site
Location: Bl	loomington, Minnesota
Identification	on Number: MND980995872
Date Plan Rec	ceived: January 24, 1989
	r: Meri K. Lapp

- 1. To adequately sample the Site, the five soil samples proposed for "unpaved areas near the restaurant" must be taken beneath any fill that is present. In general, two to five feet of fill is present on all Sites in the area.
- 2. When sampling the industrial and production wells it is important to realize that there are several other documented sources of ground water contamination in the area. Specifically, Aztec Industries and the France Avenue Drive Inn Dump.
- 3. The HRS score is based upon a municipal well located 1.5 miles from the Site. For this reason, the municipal well should be sampled along with the industrial and production wells.

MPCA Staff Comments On Screening Site Inspection Work Plan Prepared By E & E

ite Name: West 78th Circle Site
ocation: Bloomington, Minnesota
dentification Number: MND980995872
ate Plan Received: January 24, 1989
PCA Reviewer: Meri K. Lapp

- 1. To adequately sample the Site, the five soil samples proposed for "unpaved areas near the restaurant" must be taken beneath any fill that is present. In general, two to five feet of fill is present on all Sites in the area.
- 2. When sampling the industrial and production wells it is important to realize that there are several other documented sources of ground water contamination in the area. Specifically, Aztec Industries and the France Avenue Drive Inn Dump.
- 3. The HRS score is based upon a municipal well located 1.5 miles from the Site. For this reason, the municipal well should be sampled along with the industrial and production wells.

Content:

WORK PLAN

1

SITE MAPS

2

HRS WORKSHEETS 3

APPENDIX

4

WORK PLAN

SITE INSPECTION WORK PLAN

THIS DOCUMENT IS CONFIDENTIAL. Due to the predecisional nature of this document, this document and its attachments are not to be released without prior approval of the United States Environmental Protection Agency (U.S. EPA).

This site inspection work plan (VP) has been prepared by Ecology and Environment, Inc., or its subcontractor, C. C. Johnson and Kalhotra, P.C., under the field investigation team (FIT) contract with U.S. EPA (No. 68-01-7347).

The objectives of this VP are to:

- o Prepare a preliminary Hazard Ranking System (HRS) score using HRS 1 (40 CFR 300, July 16, 1982) criteria based on existing file information (Part C of VP);
- Prepare projected ERS 1 scores based on experience and professional judgement (Part C of VP);
- o Provide ERS factor values using the revised ERS 2 (Federal Register proposed date, April 1988) criteria (Part D of VP);
- o Identify HRS 1 score data gaps (Part F of VP); and
- o Propose site inspection activities to satisfy the HRS 1 score data gaps; technical approach and estimated LOB are provided (Parts F and J, respectively).

Unless otherwise stated, QA/QC protocol for site inspection activities are documented in the Quality Assurance Project Plan Region V FIT Conducted Site Inspections - Hay 1, 1987.

Note: This Work Plan has been prepared following the ERS model currently in use. Revisions will be made to bring the VP in agreement with the revised ERS requirements after promulgation in October 1988.

A. GENERAL INFORMATION

ALSO KNOWN AS: FORMERLY KNOWN AS: ADDRESS: 4470 W. 78 TH ST CITY: BLOOMINGTON STATE: MN COUNTY: HENNEPIN ZIP CODE: 55435 U.S. EPA ID: MND 980 995872 SSID: NONE TDD: F05-8706-169 PAN: FMN 0172 GA-
ADDRESS: 4470 W. 78 TH ST. CITY: BLOOMING TON STATE: MN COUNTY: HENNEPIN ZIP CODE: 55435 U.S. EPA ID: MND 980 995872 SSID: NONE TDD: F05-8706-169
CITY: BLOOMINGTON STATE: MN COUNTY: HENNEPIN ZIP CODE: 55435 U.S. EPA ID: MND 980 995872 SSID: NONE TDD: F05-8706-169
STATE: MN COUNTY: HENNEPIN ZIP CODE: 55435 U.S. EPA ID: MND 980995872 SSID: NONE TDD: F05-8706-169
COUNTY: HENNEPIN ZIP CODE: 55435 U.S. EPA ID: MND 980995872 SSID: NONE TDD: F05-8706-169
ZIP CODE: 55435 U.S. EPA ID: MND 980 995872 SSID: NONE TDD: F05-8706-169
U.S. EPA ID: MND 980 995872 SSID: NONE TDD: F05-8706-169
SSID: NONE TDD: F05-8706-169
TDD: F05-8706-169
FIT USE ONLY WORK PLAN TYPE: X SCREENING SITE INSPECTION (SSI) WORK PLAN
OTHER:
PREPARED BY: Daniel Sullivan (FIT) DATE: 10-21-88
REVIEWED BY: Kit Siml (FIT) DATE: 10-28-88
APPROVED BY: makin (FIT) DATE: 1/23/89
U.S. EPA USE ONLY
REVIEVED BY: (U.S. EPA) DATE:
WORK PLAN APPROVED. Recommend issuance of TDD to implement the Work !
WORK PLAN APPROVED. No Further Remedial Action Planned (NFRAP).
WORK PLAN REJECTED.
COHHENTS:
CORRENTS:

B. SITE INFORMATION

This section of the VP presents current and historic information pertaining to the site, including: site operations, storage/disposal methods, site property area, site status, owners and operators, permit information, and response/enforcement activities. A site location map is shown on Figure 1, located in Section 2.

	• •		
	Above ground storage		Kining site
	Below ground storage		Open dump
·	Chemical manufacturer		Ore processor
	Drum recycler		Physical/chemical treame
· 	Electroplater		Recycler/reclaimer
	Foundry Incinerator		Surface impoundment Underground injection
	Incinerator Landfarm	·	Vell field
	Landfill		Wood preserver
· 	. Hidnight dump	-	Other: RESTAURANT
	urantant gamb		Other: WEST WOUNDAIL
	•		
	The second second		·
ferences Storag	e/Disposal Methods (past a	and presen	Vaste Quantity
		and prese	Vaste Quantity
	ge/Disposal Methods (past a	and prese	Vaste Quantity
	e/Disposal Methods (past a	and prese	Vaste Quantity
	e/Disposal Kethods (past a Drums, above ground Landfarm	and prese	Vaste Quantity
	e/Disposal Methods (past a	and prese	Vaste Quantity
	e/Disposal Kethods (past a Drums, above ground Landfarm	and prese	
	pe/Disposal Methods (past a Drums, above ground Landfarm Landfill Open dump Piles	and prese	Vaste Quantity
	Drums, above ground Landfarm Landfill Open dump Piles Surface impoundment	and prese	Vaste Quantity
	pe/Disposal Methods (past a Drums, above ground Landfarm Landfill Open dump Piles	and prese	Vaste Quantity
	Drums, above ground Landfarm Landfill Open dump Piles Surface impoundment Tank, above ground	and prese	Vaste Quantity (amount/units of measure)
	Drums, above ground Landfarm Landfill Open dump Piles Surface impoundment Tank, above ground Tank, below ground	and prese	Vaste Quantity
Storag	Drums, above ground Landfarm Landfill Open dump Piles Surface impoundment Tank, above ground Tank, below ground Other: BURIED PAILS	and prese	Vaste Quantity (amount/units of measure)
	Drums, above ground Landfarm Landfill Open dump Piles Surface impoundment Tank, above ground Tank, below ground Other: BURIED PAILS	and presen	Vaste Quantity (amount/units of measure)

References:

4. Site Status: X Active	Inactive	
		· .
References:		
References:	المنابعة ال	
•		_
5. Owner/Operator History		
	•	•
Current Owner	Current Operator	
Name: SAGA CORPORATION	Name: SAME AS OWNE	R'
Address: 200 2nd Av. W	Address:	
City, State, Zip Code:	City, State, Zip Code:	
SEATTLE WA 98119 Years of Ownership:	Two of Operations	
rears of ownership:	Type of Operation: Years of Operation:	
	rears or operation.	
Previous owners	Previous operators	
(list most recent first)	(list most recent i	first)
Name: UNKNOWN Address:	Name:	
Address:	Address:	
City, State, Zip Code:	City, State, Zip Code:	
city, state, aip code.	city, state, zip code.	<u> </u>
Years of Ownership:	Type of Operation:	
en e	Years of Operation:	
	· · · · · · · · · · · · · · · · · · ·	
•		
Name:	Name:	
wagtess:	Address:	
City, State, Zip Code:	City, State, Zip Code:	
Years of Ownership:		
	Type of Operation:	<u> </u>
	Years of Operation:	
3		
References:	'''	
6. Permit Information	Effective Date Expiration	n Date
NPDES	•	
UIC		
AIR		
RCRA, PART A PART B		
SPCC PLAN		
STATE (specify):		•
LOCAL (specify): OTHER (specify):		
X NONE KNOWN		-
V Installs		•
References:		

7.	Response Activities (previous and curr all that apply):	rent site remediation; check
	Vater supply closed Temporary vater supply provided Permanent vater supply provided Spilled material removed Contaminated soil removed Vaste repackaged Vaste disposed elsewhere On-site burial In situ treatment Encapsulation Emergency vaste treatment Cutoff valls Emergency diking/surface vater diversion	Cutoff trenches/sump Subsurface cutoff vall Barrier vall constructed Capping/covering Bulk tankage repaired Grout curtain constructed Bottom sealed Gas control Fire control Leachate treatment Area evacuated Access to site restricted Population relocated
	Other remedial and enforcement activi CONTAHINATED SOIL BACK PAVED OVER AS A	KFILLED , LEUELED
Ref	•	
8.	Additional Site Information: THE 78 BY THE SAGA CORP. FOR THE CONSTRUCT ABUTS AZTEC INDUSTRIES TO THE N.E. BY THE MPGA. APPROXIMATELY 2S FIVE-GA MATERIAL WERE UNCOVERED DURING THE INSTITUTE CONTAMINATED SOIL AND LEAKING PAILS THE REMAINING PILE OF CONTAMINATED SOIL SPREAD OVER THE SURFACE AND THE SURFACE DISPOSED OF IN A DUMPSTER.	TION OF A RESTAURANT. THE SITE A FORMER SITE UNDER INVESTIGATION VLON PAILS OF A DARK VISCOUS ALLATION OF UTILITIES. MOST OF WERE BACKFILLED INTO THE TRENCH. WITH ~5 PAILS OF MATERIAL WAS
Ref	ferences:	••
9.	Documented and Alleged Target Compound Documented and alleged target compounds are from previous sampling projects. The based on the history of site operation Documented and alleged target compound the projects.	ounds are compiled in Table 1. e supported by analytical data e alleged target compounds are ons and professional judgement.

2, located in Section 2.

	CMPND	STATUS			M	ATRI	X (\	イ		DOCUMENTED COMPOUND AND CONCENTRATION OR ALLEGED COMPOUND AND RATIONALE	REFERENCE	
LOCATON	pocu	ALLEG	soil	SED	GW	SW	AIR	WSTE	OTHR	ALLEGED COMPOUND AND RATIONALE	igh enerve	
·		X	X							PCBs 28.9 PPM	3	
)		X	X							TOLUENE 94.0 PPB	3	
		X.	X							M- XYLENE 140.0 PPB	3	
		X	人					·		1,1,2- TRICHLOROETHYLENE 8500.0 PPB	. 3	
				ļ				ļ				
*								-			د و ۱۰ هست چند چند مشهوری شیرین استون بیشترین در	
								-				
											 	
											 	
				ļ								
					-							
					-							
					 				-			
												
												

Toble 1, DOCUMENTED/ALLEGED TARGET COMPOUND LIST

The purpose of this section is to:

- o Prepare a preliminary HRS 1 score based on existing file information; and
- o Prepare projected ERS 1 scores based on experience and professional judgement.

PRELIMINARY HRS SCORE (this score is based on existing file information that was obtained prior to the screening site inspection):

$$s_{H} = O s_{FE} = O s_{DC} = O$$

PROJECTED BRS SCORE FOR A SCREENING SITE INSPECTION (this score is based on the expected acquisition of information from the screening site inspection):

$$s_{H} = \frac{11.21}{s_{FE}} = \frac{0}{s_{DC}} = \frac{0}{s_{DC}}$$

PROJECTED HRS SCORE FOR A LISTING SITE INSPECTION (this score is based on the expected acquisition of information from the Listing Site Inspection):

$$s_{H} = 33.62$$
 $s_{PE} = 0$ $s_{DC} = 0$

HRS 1 score vorksheets are located in Section 3.

D. HRS 2 FACTOR SCORE

The HRS 2 factor values were computed using HRS 2 (Federal Register proposed date, April 1988) criteria. The HRS 2 factor value criteria were developed to reflect anticipated key HRS 2 scoring issues. The HRS 2 factor values have been calculated using available file information.

	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	Observed		
Factor	Factor Score	Busan Exposure		
,		(X)		
Vaste Characteristics	(100)			
Air Pathway	32.20 (100)			
Groundwater Pathway	53.22 (100)			
Surface Vater Pathway	<u> </u>			
On-site Pathway	70.00 (100)			
TOTAL ERS 2 PACTOR VALUE	155.42 (500)	-		

ERS 2 factor value vorksheets are located in Section 3.

E. VORK SUMMARY

Based on the preliminary and projected HRS scores, a site inspection will be performed.

The objectives of the site inspection are to:

- o Provide information to satisfy ERS data gaps;
- o Develop the information base needed to permit U.S. EPA to evaluate the need for future site activities; including: immediate removal measures, additional investigation, or no further action; and
- o Characterize hazardous substances, pollutant dispersal pathways, types of receptors, facility management practices, and potentially responsible parties.

Specific tasks to be conducted during the site inspection are (check all that apply):

	, radiation dete	mentation (i.e. ector, cyanide d	, ENU, OVA, O ₂ meter, etector)
		Removal Actions	
FASP*			
_ Soil gas monito			•
Vell point inst	tallation*		•
Geophysics*:			(Specify)
OTHER*:			
<u>-</u> -		<u>. </u>	· · · · · · · · · · · · · · · · · · ·
· 			
			
	 _		
	•		HPC Jata dance
tionale for these	activities and	their impact on	
tionale for these	activities and	their impact on	mm nata Rahas
tionale for these	activities and	their impact on	mm data Babs.
tionale for these	activities and	their impact on	amo data gaps.
tionale for these	activities and	their impact on	amo data gaps.
tionale for these	activities and	their impact on	ano data gaps.

	1		9
Page	1	of	_

F. PROPOSED SAMPLE PLAN

The HRS data gaps are identified in this section, and a proposed sample plan is developed based on the type of information required.

1.	A)	ERS data gap(s): WASTE CHARACTERISTICS
	В)	Sampling proposed to satisfy HRS data gap(s):
		X SoilSedimentGVSVAirVaste
	C)	Sampling procedures (number and types of samples; equipment; methodology): Collect Five soil samples from unpaved Areas NEAR THE RESTAURANT. ONE OF THE SAMPLES WILL BE A BACKGROUND SAMPLE. COLLECT SAMPLES, COMPLETE PAPERWORK, PACKAGE SAMPLES, AND SHIP TO LAB MAINTAINING CHAIN-OF-CUSTODY AT ALL TIMES.
	A -	table of proposed sample descriptions is presented in Table 2.
		etion 1. A proposed sample location map is presented in Figure 3,
		Section 2.
		i
2.	A)	ERS data gap(s): GROUNDWATER CHARACTERISTICS
	•	
	в)	Sampling proposed to satisfy ERS data gap(s):
		SoilSediment X GVSVAirVaste
	c)	Sampling procedures (number and types of samples; equipment; methodology): Collect THREE INDUSTRIAL/PRODUCTION WELL SAMPLES
		FROM FACILITIES NEAR THE SITE IN ORDER TO DETERMINE
		GROUNDWATER CHARACTERISTICS. COLLECT SAMPLES, COMPLETE PAPERWORK, PACKAGE SAMPLES, AND SHIP TO LAB MAINTAINING THE
		CHAIN - OF - CUSTODY AT ALL TIMES.
		
	A	table of proposed sample descriptions is presented in Table 2,
		ction 1. A proposed sample location map is presented in Figure 3,
		Section 2.

Note: Sample locations and/or the number of samples may be changed or eliminated at the discretion of the site team leader in response to actual site conditions during the course of the inspection.

F. PROPOSED SAMPLE PLAN (Continued)

The HRS data gaps are identified in this section, and a proposed sample plan is developed based on the type of information required.

B)	Sampling proposed to satisfy HRS data gap(s):
	SoilSedimentGVSVAirVaste
C)	Sampling procedures (number and types of samples; equipment;
	methodology): NO AIR SAMPLING WILL BE CONDUCTED AT THIS TIME. NO SURFACE WATER SAMPLING WILL BE DONE AT THIS
	TIME.
. ~	table of proposed comple descriptions is apparented in Table 2
A ~	table of proposed sample descriptions is presented in Table 2,
	table of proposed sample descriptions is presented in Table 2, tion 1. A proposed sample location map is presented on Figure 3,
Sec	tion 1. A proposed sample location map is presented on Figure 3,
Sec	
Sec	tion 1. A proposed sample location map is presented on Figure 3,
Sec in	tion 1. A proposed sample location map is presented on Figure 3,
Sec in	stion 1. A proposed sample location map is presented on Figure 3, Section 2.
Sec in	stion 1. A proposed sample location map is presented on Figure 3, Section 2.
Sec in	Section 1. A proposed sample location map is presented on Figure 3, Section 2. HRS data gap(s):
Sec in	stion 1. A proposed sample location map is presented on Figure 3, Section 2.
Sec in	Section 1. A proposed sample location map is presented on Figure 3, Section 2. HRS data gap(s):
Section A) C)	Sampling proposed to satisfy HRS data gap(s):
Section A) C)	Sampling proposed to satisfy HRS data gap(s): Soil Sediment GV SV Air Vaste Sampling procedures (number and types of samples; equipment;
Section A) C)	Sampling proposed to satisfy HRS data gap(s): Soil Sediment GV SV Air Vaste Sampling procedures (number and types of samples; equipment;
Section A) B)	Sampling proposed to satisfy HRS data gap(s): Soil Sediment GV SV Air Vaste Sampling procedures (number and types of samples; equipment;

Note: Sample locations and/or the number of samples may be changed or eliminated at the discretion of the site team leader in response

in Section 2.

			М	ATR	X (1	1		RATIONALE FOR DETERMINING SAMPLE LOCATION			PAR	AMETE	RS ¹	
LOCATION	SOIL	SED	ВW	sw	AIR	WSTE	OTHR		A/B/N	Pest/ PCB	VOA	METAL	CN ⁻	OTHER
51	X						1.	BACKGROUND SAMPLE	X	Χ	Χ	X	Х	
52	乂						1	WASTE CHARACTERISTICS	X	X	X	X	У	
53	X								X.	X	X	X	Х	
54	X					,			X	X	X	Х	Х	
55	乂					1		V	X	X	X	X	X	
.W.			Χ					GROUNDWATER CHARACTER ISTICS	X	×	X	X	X	
W2			X		-			1	文	X	X	X	X	
w3			X					. •	X	X	X	X)	X	
DUPLICATE			X					DUPLICATE SAMPLE (W2)	X	X	X	X	Х	
BLANK							X		X	X	X	X	X	
	_													
									-					
								<u></u>						
							 		+					
									-					(
									-					
. 									-					
														<u></u>
TOTALS	5		4				 		10	0	10	10	10	······································

¹Target Compound List Attached

Table 2
PROPOSED SAMPLE DESCRIPTIONS
(INCLUDING ALL LABORATORY BLANKS AND DUPLICATES)

G. COHHENTS

	H. HEALTH AND SAFETY
	·
	posed E & E Health and Safety protocol to be followed during site
ins	pection.
1.	Anticipated level of protection: A B C X D
2.	Level of protection modifications: Level D WITH POSSIBLE UPGRADE
	TO LEVEL C
3.	Work limitations (time of day, etc.): WORK DURING DAYLIGHT
	HOURS ONLY. MONITOR FOR HEAT/COLD STRESS. MAINTAIN
	THE BUDDY SYSTEM AT ALL TIMES.
	I. TYPE OF DELIVERABLE
	Proposed report format to be submitted to U.S. EPA.
	^
1.	SSI Report including U.S. EPA 2070-13 Form
2.	Letter Report
	· ·
	_ -

0365:3

SUBT ASK CODE	□ General Non-Specific	D File Search/Review	→ York Plan	○ Safety Plan	m QAPP	n Mobilization/Demobilization	G) Travel	■ Mon-Sampling Field Work	- Sample Management .	← Field Sampling	C Field Sampling . Screening/Analytical . Screening/Analytical . Screening .	☐ Subcontract	→ Meteorologic/Air Sampling Studies	Z Geophysical Work	Hydrogeological York	O Data Processing/Modelling	D Data Validation	70 Draft Final Deliverable	o Internal QA Review	→ Final Deliverable		-	דסד אנ
	D D	В	C	0	т	71	G	I		ر	κ	٦	ュ	z	0	ס	Ð	70	တ	-	C	7	ıΥ
TEAM LEADER	12	12		8		4	16			<u> </u>								60)	20	8		148
SAFETY OFFICER	•					4	16			8													28
SAMPLER							16		14														30
TEAM MEMBER		-				4	16			8								-					1
TEAM MEMBER						4	16			8													. 、
NUMIN/SAMPLE COURD	2								4														
EDIT/PUBLICATION	2																	15		IJ			22
QA/DATA REVIEW/HEALTH			·	8			-										10		25	0.			4
TOTALS FOR PROJECT	91	12		16		16	80		18	32							0	75	25	5 25	8	-	35
	ļ																						ļ

J. ESTIMATED LOE HOURS
SUMMARY OF PROJECTED HOURS NEEDED TO IMPLEMENT
SITE INSPECTION AND COMPLETE SITE INSPECTION REPORT.


SITE MAPS


*****;-


SITE MAPS


- 1. SITE LOCATION MAP (TOPO)
- 2. DOCUMENTED/ALLEGED
 TARGET COMPOUND MAP
- 3. PROPOSED SAMPLE LOCATION MAP

	ology and environ	
TITLE		FIGURE #
SITE		ECALE
CITY	STATE	P.4.H.
SOURCE		DATE
		REVISED









HRS WORKSHEETS

Hazard Ranking System 1: Score Worksheets:

PRELIMINARY AND PROJECTED HAZARD RANKING SYSTEM SCORE WORKSHEETS

Site Name:	WEST 78-	TH CIRCLE S	ITE (Cercfis Name)
		· · · · · · · · · ·	(AKA)
Address:	4470 W	. 78 TH ST.	
City/County/St	ate/Zip_BLOO	MINGTON / H	ENNEPIN / MN/55435
Cerdis ID #	MND98099		SSID NONE
Prepared by	Daniel Sul	livan E&E	Date 10-21-88
Reviewed by	Kut	ind E&E	Date 10-28-88
τοο:	F05-8706-	- 169	PAN FMN0172GA
			•
Type of Doc PA	ument		•
WP-SS	SI	X	
PRELIMINAR	Y HRS SCOR	Ε	•
S _M =(<u> </u>	S _{FE} =	S _{oc} =
PROJECTED	HRS SCORE	FOR SCREEN	ING SITE INSPECTION (SSI)
S _M = 1	1.21	S _{FE} = ()	S _{oc} =
	HRS SCORE	FOR LISTING	SITE INSPECTION (LSI)
s _m = 33	5.62	S _{FE} = ()	S _{DC} =

PRELIMINARY HRS SCORE

UNOFFCHEN STIP DRINGSACE SHE OF ROTH COMMITTED BAN THAT MOTANACHIN SHE DRIFFES IN COSEA IN SHEET

·	s	s*
Groundwater Route Score (Soc-)	0	0
Surface Water Route Score (S, -)	0	0
Air Route Score (S ₄ -1	0	0
Sout + Sout + SA		
$\sqrt{S_{QM}^2 + S_{QM}^2 + S_A^2}$		
V Sex + Sex + SA / 173 - SM-		0

PROJECTED HRS SCORE FOR SCREENING SITE INSPECTION (SSD

THUS SCORE IS BASED ON THE EXPECTED ACQUISITION OF INFORMATION PROM THE BEREEMING BITE INSPECTIONAL

·	s	s*
Groundwater Route Score (Spen)	19.39	375.97
Surface Water Route Score (S)		0
Air Route Score (S _A -)	0	0
Sex + Sex + Se		375.97
$\sqrt{S_{\phi \pi}^2 + S_{\phi \pi}^2 + S_{A}^2}$		19.39
V St + St + St / 1.73 - SH -		11.21

PROJECTED HRS SCORE FOR LISTING SITE INSPECTION (LSD

ITHE BOOME IS BASED ON THE EXPECTED AGUSTION OF BYPORMATION FROM THE LISTING SITE BISPECTION.)

	s	s ^e
Groundwater Route Score (S)	58.16	3382.59
Surface Water Route Score (S _{ee} -)	0	. 6
Air Route Score (S ₄ -)	0	0
St. + St. + St.		3382.59
$\sqrt{S_{ow}^2 + S_{pw}^2 + S_A^2}$		58.16
$\sqrt{S_{ov}^2 + S_{pe}^2 + S_A^2} / 1.73 - S_M -$		33.62

GROUNDWATER ROUTE

	PRELIMINARY HRS	SCORE	WORKS	HEET	
(This so	ore is based on existing prior to the Screen	_			
Rating Factor	Assigned Value (Circle One)	Multi- plier	Score	Description	Ret. #
Observed Release (o) . 45	x1	0	NONE OBSERVED	
If Observed Release soon	res 45 proceed to line 4				
2 Route Characteristics				Aquider Description:	
-				JORDAN	_
Depth to Aquiler of concern	0) 1 2 3	12	0	360 n	1
Net Precipitation	0(1) 2 3	x 1	1	Precip 28.41 Evap 30.25"	2.
Permeability of the Unsaturated Zone	o (i) 2 3	x1		10.6 cm/sec -	ľ
Physical State	0 1 2(3)	xt	3	SLUDGE	3
	Total Route Char, Score		5		
3 Containment	0 1 2(3)	মা	3	LEAKING PAILS	4
Waste Characteristics	•			e Are	-
Persistance 0	0 0 0				
loxicity 1 3	9 12 9 12 15 2 15 18	x1	0	UNKNOWN	•
Haz. Waste Quantity	012345678	x1	0	UNKNOWN	
	Total Waste Char, Scor	•	0		
S Targets					
Groundwater Use Distance to	0 1 2(3)	x 3	9	DRINKING	1-
Nezrest Well 0	0 0 0 0 0	·		~ 1.5 MILES	1,5
Population 2 Served 4	0 8 12 16 20 0 12 18 24 30				
Served 4	0 16 24 32 35 0 20 30 35 40	_ x1	30	~162682	6
i	Total Targets Score		39		
6 It line 11 is 45, multiply It line 11 is 0, multiply		-	0		
Divide line d by Si	7,330 and multiply by 100)	S _{gw} =	0.00	

10

GROUNDWATER ROUTE

				NG SITE INSPECTION (S	
(This score is based on			nation fr	om the Screening Site insp	ection.i
Rating Factor	Assigned Value (Circle One)	Multi- plier	Score	Description	Ref. #
1 Observed Release	0 , 45	· x1	0		
# Observed Release sco # Observed Release sco	res 45 proceed to line 4				
2 Route Characteristics				Aquiter Description:	
· '7				JORDAN	
Depth to Aquiter of concern	(e) 1 2 3	n	0	360 ft.	1
Net Precipitation	0 12 3	ম	1	Precip 28.41" Evap 30 25"	2
Permeability of the Unsaturated Zone	0(1)2 3	χt	1	10° cm/sec	1
Physical State	0 1 23	n	3	SLUDGE	3
·	Total Route Char. Scor	q	5		
3 Containment	0 1 23	. પ્રા	3	LEAKING PAILS	4
4 Waste Characteristics					
Persistence 0	1 2 3				
Toxicity 1 3	0 0 0 6 9 12 9 12 15	x1	18	ASSUME PCBS	3
3 9 Haz. Waste Quantity	12 15 (18) (0(1)2 3 4 5 6 7 8	3 · x1	1	~ 150 GALLONS	3
	Total Waste Char, Soo	KO	19		
S Targets	·!				
Groundwater Use	0 1 2(3)	x 3	9	DRINKING	1-
Distance to Nearest Well	0 1 2 3 4		ــــــــــــــــــــــــــــــــــــــ		15
1	0 4 6 8 10 0 8 12 16 20			~ 1.5 MILES	1,5
Population 2 Served 4	0 12 18 24 30 0 16 24 32 35	_		1/0/02	
. 5	0 20 (30) 35 40	<u> </u>	30	~ 162682	6
	Total Targets Score		39	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	
6 # line 11 is 45, multiply			11115		
Divide line (by S	57,330 and multiply by 10	××	Sg#	19.39	

GROUNDWATER ROUTE

•					G SITE INSPECTION (LSI from the Usting Site Inspec	1
Rating Factor	Assigned Value (Circle One)		Multi- plier	Score	Description	Ref. #
1 Observed Release	0 (45)		. x1	45		
If Observed Release so	ores 45 proceed to	line 2				
2 Route Characteristics					Aquiler Description:	
•		•				
Depth to Aquiler of concern	0 1 2 3		12		ft.	
Net Precipitation	0.123		xi		Precip Evap	
Permeability of the Unsaturated Zone	0123		xi	-	cm/sec	
Physical State	0123		x1			
	Total Route Cha	ar. Score				
3 Containment	0 1 2 3	·	xı		·	
Waste Characteristics		Apr. 7 IM d				·
Persistence 0	1 2 3	*				
Toxicity 1 3 2 6 - 3 9	0 0 0 6 9 12 9 12 15 12 15 18	•	x1	18	ASSUME PCBs	3
Hzz. Waste Quantin	4 A /	678	x1	5	~ 150 GALLONS	3
	Total Waste Ci	har, Score		19		
S Targets	<i>c</i>	···	 -	-		
Groundwater Use Distance to	0 1 2(3)		- x3	. 9	DRINKING	1
Nezrest Well 0	0 1 2 3	4 0 10	·		~ 1.5 MILES	1,5
Population 2 Served 4	0 8 12 16 1 0 12 18 24	20 · 30				
561760 4	0 16 24 32 30 35	35 4 0	x t	30	~ 162682	6
	Total Targets	Score		39		11111111111111111111111111111111111111
6 It line 1 is 45, multiply It line 1 is 0, multiply		<u> </u>		33345		
Divide line d by s				S _{gw} =	58.16	-

SURFACE WATER ROUTE

<u></u>						
PRELIMINARY HRS SCORE WORKSHEET (This score is based on existing fits information that was obtained prior to the Screening Site inspection.)						
Rating Factor	Assigned. Value (Circle One)	Multi- plier	Score	Description	Ref. #	
1 Observed Release	(0) 45	x 1	0			
II Observed Release so II Observed Release so						
2 Route Characteristics	Intervening Terrain	•		Facil O %	5	
Fac	0 0 0 0 3 Aug 0 1 1 2 3	. x1	0	Interv 0 %	5	
Stop	Pe 0 1 2 2 3 0 2 2 3 3 0 2 3 3 3					
1-yr. 24 hr Rainfa	•	x 1	2	2.35 ia.	2	
Distance to Neares Surface Water	đ 0(1)2 3	x 2	2	~ /4 MILE	5	
Physical State	0 1 2(3)	x t	3	SLUDGE	.3	
·	Total Route Char, Score		7			
3 Containment	0 1 2 3	x1	3	LEAKING PAILS	4	
4 Waste Characteristics		_		//////////////////////////////////////		
Persistence 0 1 2 3						
Toxicity 0 0 3	0 0 0					
	9 12-15	x 1	0	UNKNOWN		
Haz. Waste Quantit	012345678	x1	0	UNKNOWN		
	- Total Waste Char, Scot	re	0			
S Targets	•	•	. •	//////////////////////////////////////		
Sudace Water Use	0123	x3	0	HONE KHOWH		
Dist to Sensitive Environment	0 1 2 3 Distance to Water	x2	Ö	N/A		
	Intake Downstream					
Populatio	0 4 6 8 10 x1 0 8 12 16 20					
Served	0 12 18 24 30 0 16 24 32 35	x 1	(2)	N/A		
	Total Targets Score		0	/ n		
6 If line 11 is 45, multiple						
If fine [] is 0, multiply			0			
Divide line (by 64,3	350 and multiply by 100	Ssw	• 0			

UNLIKELY THAT SURFACE WATER RELEASE HAS OCCURRED ... THE CONTAMINATED AREA OF PROPERTY HAS BEEN PAVED OVER.

99

SURFACE WATER ROUTE

	SURFACE V	MILLI	1001		
			•	ING SITE INSPECTION (Storem the Screening Site Insp	1
	Assigned Value	Multi-			
Rating Factor	(Circle One)	plier	Score	Description	Ref. #
Observed Release	0 45	x 1			
t. Observed Release scores 45 proceed to line 2 .					
2 Route Characteristics	Intervening Terrain	-		Facil %	
Facili	0 0 0 0 3 sy 0 1 1 2 3	x t		latery %	
Stope	102233			**************************************	
1-yr. 24 hr Rainfall	02333	x1		ia	
Distance to Nearest Surface Water	0123	x 2			·
Physical State	0123	x 1		-	•
	Total Route Char, Score				
3 Containment	0123	.x1			
4 Waste Characteristics		لـــــــــــــــــــــــــــــــــــــ	L		
0	1 2 3				
0.0	0 0 0			i	
Toxicity 1 3 6	6 9 12	x t			
Haz. Waste Quantity	012345678	×1	-		
	Total Waste Char. Soo	(CO			
ิต-					
S Targets	•		· · · · · · · · · · · · · · · · · · ·		
Sudace Water Use	0123	x 3			·
Dist to Sensitive Environment	O 1 2 3 Ostance to Water	x 2		·	
	Intake Downstream 0 0 0 0 0 0 4 6 8 10				
Population	0 8 12 16 20				1
Served	0 12 18 24 30 0 16 24 32 35 0 20 30 35 40	x 1			
	Total Targets Score				
6 & line 11 is 45, multiply	1x4xS		1		~~~~~~~~~~~ ~~~~~~~~~~~~~~~~~~~~~~~~~~
E line [] is 0, audiply	2x 8x 4x8	····	<u> </u>		
Divide line d by 64,35	io and multiply by 100	Ssw			

SURFACE WATER ROUTE

		E WATER			
PROJECTED I	HRS SCORE WORKS	SHEET FOR	LISTING	SITE INSPECTION (LSI)	
				rom the Listing Site inspec	
Rating Factor	Assigned Value (Circle One)	Multi- plier	Score	Cescription	Ref. #
1 Observed Release	0 45	x 1			
ti Observed Release scores 45 proceed to line 4 ti Observed Release scores 0 proceed to line 2					
2 Route Characteristics Intervening Terrain				Facil	
F	0 0 0 0 3 acidy 0 1 1 2 3	x1		latery %	
· s	tope 0 1 2 2 3 0 2 2 3 3 0 2 3 3 3				111111111111
1-yr. 24 fir Rain		x 1		ir.	
Distance to Near Surface Wate	est 0123	x2			
Physical State	0123	x1		·	
	Total Route Char.	Score			11111111111111
3 Containment	0123	χí			
4 Waste Characteristics					1111111111111
Persistence 0 1 2 3				<u> </u>	
Toxicity 0 0 2 0 1 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0	6 9 12	x1		<u> </u>	
2 6 3 9 Haz. Waste Quar		78 x1			
	Total Waste Char.				
ল			L		
S Targets		•	. .		
Surface Water U	_	x3			<u> </u>
Dist to Sensitive Environment	Distance to Water	x2	•		
	Intake Downstream	•			<i>.,,,,,,,,,,,,,</i> ,,,,,,,,,,,,,,,,,,,,,,,
Popula Serve	0 4 6 8 10 dion 0 8 12 16 20 ed 0 12 18 24 30				
30.11	0 16 24 32 35 0 20 30 35 40	x1			
	Total Targets Soo	X4			
6 t line [] is 45, multiple [] is 0, multip	ipy (Ix 4 x S by 2 x 3 x 4 x S				
Divide line (d) by 6	4,350 and multiply by 10	00 S _{s w} .	• 0		'

AIR ROUTE

· ·	PRELIMINARY HRS		-	•	
(This	s score is based on existing prior to the Screen				
Rating Factor	Assigned Value (Circle One)	Multi- plier	Score	Description	Ref. #
(i) Observed Release	6 45	x 1	0		
t kne 1 is 0, the Sa t line 1 is 45, then	-0. Enter on line 5 proceed to line 2				
Waste Characteristic	s				
Reactivity & Incompatability	0 1 2 3	ĸ1			
Toxicity	0 1 2 3	x 3			
Haz. Waste Quanti	A 0 1 2 3 4 5 6 7 8	x1			
·	Total Waste Char. Soo	×e			
3 Targets Population within 4-mile Radius	Dist to Population 0 0 0 0 9 12 15 18 12 15 18 21 Pop 15 18 21 24				
Distance to Sensiti	18 21 24 27 21 24 27 30	x t	 		
Environment	o 123	x 2			
Land Use	0 1 2 3	x t			
	Total Targets Score				
E restipy 11x2x	3				
Divide line 4 by 3s	5,100 and multiply by 100		S _a =	0	

NO AIR DATA AVAILABLE

					
				ING SITE INSPECTION (S	1
(This score is based of	offishipps betoegxe and no	a of Inform	mation fo	rom the Screening Site insp	ection.1
Rating Factor	Assigned Value (Circle One)	Multi- plier	Score	Description	Ref. #
1 Observed Release	(0) 45	x1	0		
If line 1 is 0, the Sa If line 1 is 45, then	=0. Enter on line 5 proceed to line 2				
2 Waste Characteristic	s				
Reactivity & Incompatability	0 1 2 3	x 1		e	
Toxicity	0 1 2 3	x 3			
Haz. Waste Quanti	ay 012345678	x1			
-	Total Waste Char. Sco	ке			
3 Targets Population within 4-mile Radius	Oist to Population 0 0 0 0 9 12 15 18 12 15 18 21 Pop 15 18 21 24 18 21 24 27 21 24 27 30	x t			
Distance to Sensiti Environment	ve 0 1 2 3	x 2			
Land Use	0 1 2 3	x 1			
	Total Targets Score				
A Hothiphy [] x [] x [3				
Divide line 4 by 35	i,100 and multiply by 100		S _a =	O	· <u>-</u>

NO AIR MONITORING WILL BE DONE AT THIS TIME.

AIR ROUTE

	n the expected aquisiti Assigned Value	on of Info		SITE INSPECTION (LSI from the Usting Site Inspe	_
	(Circle One)	plier			1
1 Observed Release	9) 45	. xi	0		1
If line 11 is 0, the Sa=0. If line 11 is 45, then pro	Enter on line 5 ceed to line 2	•			
2 Waste Characteristics					1001001001 1001001001
Reactivity & Incompatability	0 1 2 3	x 1			
Toxicity	0 1 2 3	x 3			 -
Haz. Waste Quantity	012345678	x1			
	Total Waste Char. Soo	Ke .			
3 Targets Population within 4-mile Radius Po	Dist to Population 0 0 0 0 9 12 15 18 12 15 18 21 P15 18 21 24				
<u>_</u>	18 21 24 27 21 24 27 30	x1		-	<u>.</u>
Distance to Sensitive Environment	0 1 2 3	x2			
Land Use	0.4.2.3	x1			
	Total Targets Score				
区 Kathiply [] x ② x ③					
Divide line 4 by 35,10	00 and multiply by 100		S _a =	\Diamond	•

INSUFFICIENT INFORMATION TO SCORE THIS ROUTE AT THIS TIME.

FIRE AND EXPLOSION

	רותכ	AND EXPL	<u>021014</u>		
(This so			formation	that was obtained	
Rating Factor	Assigned Value (Circle One)	Multi- plier	Score	Description	Ref. #
1 Containment	0 3	x1			
2 Waste Characteristics		•	-		00000000000
Direct Evidence	0 3	x1			
Ignitability	0 1 2 3	x 1			
Reactivity.	0 1 2 3	x 1			
Incompatability	0 1 2 3 .	x 1			
Haz. Waste Quantity	0 1 2 3 4 5 6 7	78 x1			
3 Targets	Total Waste Char.	. Score			
Dist to Nearest Pop.	0 1 2 3 4	5 x1	ſ 		
Office to Nearest Bldg.					
_	0 1 2 3	x1		· · · · ·	
Dist. to Sensitive Env.		×1			}
Land Use	0 1 2 3	x1		<u> </u>	·}
Pop. Vlahin 2 miles	0 1 2 3 4	·\$ x1			
Blogs. Wahin 2 miles	0 1 2 3 4	5 x1		- ··	
	Total Targets So	0(4			
4 Multiply [] x 2 x 3					
Divide line 4 by 1,440	and multiply by 10	o S ₍	£= 0	· ·	

UNLIKELY THAT FIRE AND EXPLOSION HAZARD EXISTS... THE CONTAMINATED AREA OF PROPERTY HAS BEEN PAVED' OVER.

FIRE AND EXPLOSION

				CALL	<u> </u>		
						NING SITE INSPECTION (
Rating Factor		ed Value		Multi- plier	Score	Description	Ref. #
1 Containment	0	3		хí			
2 Waste Characteristics	- .			• •			11111111111
Direct Evidence	0	3		x1			
lgnitability	0 1 2	3		x 1			
Reactivity_	0 1 2	3		x1			_
Incompatability	0 1 2	: 3	•	x 1		·	
Haz. Waste Quantity	0123	456	7 8	x1			
	Total V	lesse Cha	ır. Soor	•			
3 Targets ·					•		
Dist. to Nearest Pop.	0 1	2 3	4 5	x 1			
Dist. to Nearest Bldg.	0 1	2 3		x 1			
Dist. to Sensitive Em	. 0 ,1	2.3	•	x 1		7 (A)	
Land Use	0 1	2 3	i	x1			
Pop. Within 2 miles	0 1	2 3	4 5	x1			
Blogs. Within 2 miles	0 1	2 3	4 5	x t			
	Total 1	Tergets S	icore				
Muttiply [] x 2 x 3							
S Divide line 4 by 1.44	0 and mut	lipsy by 1	00.	s	e C)	

FIRE AND EXPLOSION

		1 11112 711	AD EXEC	00.0.		
					G SITE INSPECTION (L from the Usting Site Ins	
Rating Factor		ned Value de One)	Multi- plier	Score	Description	Ref. #
1 Containment	0	3	, x1			
2 Waste Characteristic	s		•			
Direct Evidence	0	. 3	x 1			
Igaitability	0 1	2 3	x t		~	
Reactivity .	0 1	2 3	x 1	<i>:</i>		
Incompatability	0 1	2 3	x 1			
Haz_Waste Quant	ty 0 1 2	3 4 5 6 7	8 x1		·	•
3 Targets	Total	Waste Char. S	core			
<u> </u>			-			
Dist. to Nearest Po	P- 0	1 2 3 4	s x1		·	
Dist. to Nearest Bl	dg. o	1 2 3 .	x1			
Dist. to Sensitive E	. 0 .	1 2 3	x1			
Land Use	0	1 2 3	x 1			
Pop. Wehin 2 miles	, 0	1 2 3 4	S x1	<u> </u>		
Blogs. Wahin 2 mil	es 0	1 2 3 4	5 x1	<u>. </u>		-
	Tota	l Targets Score	•			
Muttiply [] x [] x	3					
S Divide line 4 by 1,	440 and m	ultiply by 100°	· S	fe " (

DIRECT CONTACT

·								
PRELIMINARY HRS SCORE WORKSHEET (This score is based on existing file information that was cotained prior to the Screening Site inspection.)								
Rating Factor	Assigned Value (Circle One)	Multi- plier	Score	Lescription	Ref. #			
1 Observed Incident	(a) 45	x1	0	NONE OBSERVED				
If line 1 is 45, proceed to line 1 is 0, proceed	eed to line 2							
2 Accessibility	0 1 2 (3)	x 1	3	NO BARRIERS	3			
3 Containment	(0) 15	x1	0	PAVED OVER				
Waste Characterista	3							
Toxicity .	0 1 2 3	x 5	0	-UNKNOWN				
S Targets								
Pop. Wahin 1 mile	0 1 2 3 4 5	` x 4	16	~ 8046	5,6			
Dist to Crit Habit	lat (i) 1 2 3	x 4	0	N/A				
·	Total Targets Score		16					
6 If line 11 is 45, multiple to time 11 is 0, multiple	ey []x4xs y 2x8x4xs		0					
Divide line 6 by 2	1,600 and multiply by 100	S	c= C	0.00				

DIRECT CONTACT

Rating Factor	Assigned Value (Circle One)	Lulti- plier	Score	Description	Rei e
Observed Incident	0 45	x 1	0		
If line 1 is 45, proceed to line 1 is 0, proceed	eed to fine 4 ed to fine 2	•			
2 Accessibility	0 1 2 3	x1	3	NO BARRIERS	3
3 Containment	0 15	x1	0	PAVED OVER	
(Waste Characterizion	3		· · · · · ·		
Toxicity .	0 1 2 3	x5	15	ASSUME PCBS	-3
S Targets					
Pop. Within 1 mile	0 1 2 3 4 5	x 4	16	~ 8046	5,6
Dist. to Crit. Habit	at 0 1 2 3	x 4	0	NA	
·	Total Targets Score		.16		
6 If line 11 is 45, multi	ey Uxaxs y Zxbxaxs		0		

DIRECT CONTACT

				G SITE INSPECTION (LS	
Rating Factor	Assigned Value (Circle One)	Multi- plier	Score	Description	Ref. #
1 Observed Incident	o 45.	x 1	0		
If line 1 is 45, proce	eed to line 2	·			
2 Accessibility	0 1 2 3	x 1	3	NO BARRIERS	3
3 Containment	0 15	x 1	.0	PAVED OVER	·
4 Waste Characteristic	a				
Toxicity _	0 1 2 3	x 5	15	ASSUME -PCBs	3
S Targets					
Pop. Within 1 mile	0 1 2 3 4 5	x4	16	~8046	5,6
Dist to Cat. Habi	121(0) 1 2 3	x 4	0	N/A	
,	Total Targets Score		16		
6 It line 11 is 45, multip	ipy		0.		
Divide line 6 by 2	1,600 and multiply by 100	S	c= 0	.00	

Hazard Ranking System 2 Factor Value Worksheets

ERS 2- FACTOR VALUE

Factor	Factor Value	Observed Human Exposure (X)
Vasté Characteristics	(100)	
Air Pathyay	32.26 (100)	
Groundvater Pathvay	53.22 (100)	
Surface Vater Pathvay	(100)	
On-site Pathway	70.00 (100)	1
	:	•
TOTAL ERS 2 FACTOR VALUE	155.42 (500)	

WASTE CHARACTERISTICS

					factor
			Yes	Reference	Value
			(x)		
1.	(4)	Are CONTAINERS open, unsealed, or			<u></u>
		non-intact?	_		U (5)
	сьi	Is there evidence of contaminant			
	•-•	migration away from the containers?	~	-	(5)
	(-1	Is the source(s) unlined or does it	— ,		
		have unsound diking?	-		(5)
		"			
2 -	(-1	Does the LARDFILL have exposed			***
- -		waste, or is the landfill uncovered			
		or is the landfill covered with	•	•	
		_			
	•	contaminated soil, non-intact cover	_	•	· ()
		or cover less than 1 inch?			(2)
	(p)	Is there evidence of contaminant	_		^
		migration away from the source?			(S)
	(c)	Is there an absence of a liner, a			
		run-on or runoff management system			
		or leachate collection and removel			Λ
-		system?			(5)
		•			
3.	(4)	Is the SURFACE IMPOUNDMENT wet			\wedge
		and non-enclosed?			(5)
	(b)	Is there evidence of contaminant			G
		migration away from the source?			<u> </u>
	(c)	Is there so liner or diking?	=		<u>O</u> (5)
۹.	(4)	Is the PILE uncovered, or is the			
		pile covered with contaminated soil	•		
		non-intact cover or cover less than			
		1 inch?	-		(5).
	(b)	Is there an absence of a function-			
	,	ing sun-on or susoff management			
		system or leachate collection			
		system?	· —		() (5)
	(c)	Is there an absence of a liner?			0 (5)
	, . ,	•			
S _	Onl	y answer highest factor value			• •
		the following questions:			
		Is constituent data available			
	\-/	for waste?	_		0 (10)
	/h:	Is vaste quantity as deposited			(10)
	(0)	information available?	_		Ó m
					
		Is disposable volume known?			0 (4)
	(0)	Is disposable area known?			O (21

...Continued

WASTE CHARACTERISTICS (Continued)

 Complete the table for all sources at the site. Calculate Waste Quantity score and record summation to a maximum value of 30.

Source	Surface Area (ft2)	+	Divisor	-	Waste Quantity Score
Pile		•	45	_	
Drums/Non-drum Container		•	233	_	
Surface Impoundment		•	375	-	
Land Treatment	<u> </u>	٠	27,000	_	
Landfill	-	+	\$5,666		·
Conteminated Soil		•	1,125,000	_	• •

Total	0	0	(30max)
		,	
Potal Wasto Char	acteristics	0	_ (100)

AIR PATEWAY

Reference Velue. 1. Only assign factor value for (a) or (b), ·(x) choosing the higher value: (a) Is there a residence or regularly occupied building between 0 to 1/8 mile from a potential source(s)? (b) Is there a residence or regularly occupied building between 1/8 to 2 miles from a potential source(s)? 2. Complete (a) and (b) and assign the higher fector value: (a) If documented contamination of air, answer yes and assign factor value of 75. (b) Calculate potential population and assign factor walue as given below:

Distance (mile)	Population	x	Distance Weighting Factor		Subtotal
Onsite	UNKNOWN	¥	1.662	-	
0-1/4	575	*	0.323	-	185.73
1/4-1/2	1573	*	0.056	-	88.09
1/2-1	5898	×	0.017	-	100.27
1-2	18346	Z.	0.005	-	91.73
2-3	45024	z	0.003	-	135.07
3-4	59329	×	0.002	-	118.66

÷.

Total 719.55 x 1 = 7.20 (75max)

Total Mir Fathway Value 32.20 (100)

				ractor
		Yes	Reference	Value
		(x)		
1.	Is the depth to the aquifer of concern less than 800 feet?	X		5.
2.	(a) Within 2 miles of the mite,	:		
	is the geologic material between the	•		
	waste and the aquifer of concern			
	composed predominantly of sands, gravels,			4
	sandstone, limestone or dolomite?	_		<u>O</u> (5)
	(b) Within 2 miles of the site,		•	
	is there evidence of a low hydraulic			
	conductivity layer (10 ⁻⁶ to 10 ⁻⁹)between			• •
•	the waste and the aquifer of concern?			(-15)
3.				
	choosing the <u>higher</u> value: (a) is there a drinking vater well(s) in the			
	• •			_
	aquifer of concern or a more shallow unit 0 to 1/2 mile from the source(s)?	_		() (29)
	- Co 1/2 atta tron the source(s)?			(20)
	(b)- Is there a drinking vater well(s) in the			
	aquifer of concern or a more shallow unit	٠,	1 =	_
	1/2 to 2 miles from the source(s)?	<u>X</u>	1,2	<u></u>
4.	Is the aquifer of concern a karst unit?	<u>-</u>		(10)
5.	Is the aquifer of concern a sole	,		
	source aquifer?	_		(5)
6.	Complete (a) and (b), and assign the higher			
	factor value:			
	(a) If documented contamination of drinking	retes		
	wells with TCL compounds, answer yes and	_		\Diamond
	assign a factor value of 50.			<u>(50)</u>
	(b) Calculate potential population and	_		
	ander forter males as often balance			

Distance	{	1	Distance	1	
(=ile)	Population	R.	Weighting Factor	-	Subtotal
0-1/4	575	X	0.25	-	143.75
1/4-1/2	1573	ĸ	0.16	-	251.68
1/2-1	5898	×	0.08	-	471.84
1-2	18346	x	0.05	-	917.30
2-3	45024	ĸ	0.03	_	1350.72
3-4	59329	x	0.02	-	1186.58

Total 4321.87 x 1 =43.22 (50max)

SURFACE WATER PATEMAY

				Factor
	•	Yes (x)	Reference	<u>Velue</u>
1.	Does site lie within a 100-year or less floodplain?	· —		(5)
2.	Is there contamination attributable to the site at a drinking water intake?	· <u>~</u>		<u>O</u> (20)
3.	Is this a sole-source surface water supply?			6 (10)
4.	Is a fishery (production) contaminated as a of the site, or is a fishery potentially imputhin 15 miles as a result of the site?		· ·	<u>(5)</u>
5.	Is a recreation area contaminated as a result the site, or is a recreation area potentially impacted within 15 miles as a result of the	Y :		<u>(5)</u>
٤.	Is a sensitive environment contaminated as a result of the site, or is a sensitive environment of the site?	nment :		(5)
7.	Complete (a) and (b), and essign the higher factor value: (a) If there is documented contamination of surface vater intake with TCL compounds answer yes and assign a factor value of	50		<u>(50)</u>
	(b) Calculate potential population and assign	n'a .		

Intake	Population	×	• Dilution Weighting Factor	_	Subtotal
61		×	-	-	
† 2		×		-	
43		×		-	
<u> </u>		x		-	
		z		-	
		×		-	

^{*} Use table on following page.

Total_	0	x_1 =_	O (SOBAK	,
		100		

TOTAL SURFACE	WATER	PATTICULE	WAT 115	(100)
TOTAL SOM MCE	MAYER	BYTHAYI	AYTOR	 (100)

SURFACE WATER PATEWAY

TABLE DILUTION WEIGHTING FACTORS

	Averege Annuel	****
Surface _	Flow in Cubic .	Assigned
Characteristic	Feet per Second (CFS)	Velue
- · · · · · · ·		•
Minimum perennial stream	Less than S ofs	2.5
Small to moderate stream	S to S0 cfs	0.25
Koderate to large stream	Greater than 50 to 500 cfs	0.025
Large streams to rivers	Greater than 500 to 10,000 cfs	0.0013
Kajor rivers	Greater than 10,000 cfs	0.0003
Ocean or the Great Lakes	Not applicable	0.0003
Mixing zone of quiet flowing rivers	Greater than 50 cfs	0.125
Lakes, reservoirs	Add and average CFS of	Assign value
	tributeries flowing into	to calculated
	lake/reservoir.	CFS figure
•		using above
		factors.

			Factor
	Yes (x)	Reference	Value,
. Is the site located in an area where	,		
people live or go to school within 1	. v	_	10
sile of the source(s)?	. 🔼		10 (20)
"If answer 80 to Question 1, do not	• .		
proceed with the remaining questions.			
. Is there known contamination from the			
site on sesidential or school			^
property?		•	U (15)
. Is site public use land or	~	7	10
videly used land without barriers?			10(10)
. Complete (a), (b) and (c), and assign the			
highest factor value:			
Which of the following are adjacent to site/sou	(E)		
or contaminated from the site?			•
(a) Schools, day-care			<u>U</u> (15)
(b) Parks, playgrounds, residences	_		0 (10)
(c) National park, federal endangered		•	^
species, other public-use lands.		\ · ·	U (51

5. Calculate population within I mile of the site, and assign factor value as given below:

Distance (mile)	Population		Distance Weighting Factor	-	Subtotal
0-1/4	575	×	0.05	-	28.75
1/4-1/2	1573	×	0.025	-	39.33
1/2-1	5898	*	0.0125	-	73.13

Total 141.81 50 (50max)

APPENDIX

REFERENCES

SOURCES AND DATES OF INFORMATION COLLECTION

SOURCE	DATE
 State Hazardous/Solid Waste Files State Water Files 	
3) State Air Files	
4) State Department of Health	
5) State Geological Survey	
6) State Department of Natural Resources	
7) State Fire Harshall	
8) County Department of Health	•
9) County Engineer	
10) County Clerk/Recorder of Deeds	÷
11) City Department of Health	
12) City Engineer	
13) City Fire Department/Fire Karshall	
14) City Water/Sever Department	10-12 10-13-88
15) U.S. Soil Conservation Service	
16) Others	
	·
STATE CONTACT(S): RON SWENSON	(612) 297-1793
(name)	(phone number)
ELIZABETH A. GAWRYS	(612) 297-1796
(name)	(phone number)

REFERENCE DOCUMENTATION SHEET

Re1.#	DESCRIPTION OF REFERENCE			
1	MINNESOTA GEOLOGICAL SURVEY MUNICIPAL			
	WELL LOGS; BLOOMINGTON AND EDINA, MN.			
	<u>.</u>			
	•			
2	U.S. DEPT. OF COMMERCE; GOVT. PRINTING			
	OFFICE 1963. RAINFALL FREQUENCY ATLAS.			
	TECHNICAL PAPER # 40, WASHINGTON D.C.			
	PP 43 AND 68.			
-	· · · · · · · · · · · · · · · · · · ·			
3	POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY			
	ASSESSMENT; WEST 78TH CIRCLE SITE			
	ELIZABETH A. GAWRYS MPCA 12-13-84.			
4	LETTER FROM LARRY HOSKINS, TORRE CONSTRUCTION			
	Co., TO JOHN K. NELSON, DEPT. OF			
ę.	COMMUNITY DEVELOPMENT, 8-20-84.			

REFERENCE DOCUMENTATION SHEET

•=-	Re1.#	DESCRIPTION OF REFERENCE
	5	USGS TOPOGRAPHIC MAP. BLOGMINGTON MN
		QUADRANGLE 7.5 MINUTE SERIES, 1967 REV.
		1980.
	,	
•	6	1980 CENSUS OF POPULATION, U.S. DEPT. OF
		COMMERCE BUREAU OF THE CENSUS.
,		
•		
·	-	
•		to the second se
SEASON SEED SEEDS	×7	LETTER FROM JOHN M. HUNT BLACK ANGUS
		ENTERPRISES TO ELIZABETH GAWRYS MPCA,
		10-31-84.
	-	
		,
i -	÷	
		•

Copies of the following addenda have been supplied to the U.S. Environmental Protection Agency and the appropriate state agencies. Refer to these addenda when reviewing this work plan.

Addendum	Title
(A)	Routine Analytical Services Contract Required Detection and Quantitation Limits
B	Central Regional Laboratory Detection Limits
C	Special Analytical Services Detection Limits Drinking Vater Samples
D	Special Analytical Services Detection Limits Bigh Concentration Samples